1. Pull the 6 locking tabs into the notch spaces on both side of the CPU module

2. Remove the CPU module away from the base of unit.

3. Mount the SSD card with the 2 supplied 2.6φ spring washers and 2 supplied M2.6 x 4L screws

Screw with spring washer

4. Align circuit card with slot and press firmly

5. Pull locking tabs toward the face of base on both side of the CPU module