How to enter characters without a keyboard

Applies to:

Platform	OS Version	PAC Utility Version
WinPAC	All Versions	All Versions
ViewPAC	All Versions	All Versions

The WinPAC/ViewPAC only has one USB port; if there is no USB hub available for a keyboard, Win CE provides an input panel to enter characters with a mouse or on touch panel.

To enter characters without a keyboard, perform the following steps:

Step 1: Click the icon circled in the picture below.

The input panel is shown as below:

Step 2: Click the key for the character you want to enter on the Input Panel.