Classification	System and Application FAQ on WinCE PAC				No.	2-006-00	
Author	Eric_Shiu	Version	1.0.0	Date	2018/04/27	Page	1/3

## How to recover the default factory settings

ersion PAC Utility Version
rsions All Versions
rsions All Versions

## **Tips & Warnings**



The following settings are affected in the recovery operation. Before recovering the default factory settings, record the current settings if necessary.

Default factory settings:

System Settings->Display resolution: 800\*600(WP-8x2x/WP-9000/WP523x) System Settings->Display resolution: 800\*480(VP-2201) System Settings->Display resolution: 640\*480(VP-1231) System Settings->Display resolution: 800\*600(VP-4231/VP-4201) System Settings->Display resolution: 1024\*768(VP-6231/VP-6201) Ethernet Settings->LAN1 (LAN2): DHCP enabled FTP Settings->Access->Allow Anonymous: Enabled FTP Settings->Access->Allow Anonymous Upload: Enabled Auto Execution: empty Multi-serial port wizard: uninstalled Touch Panel Drivers: uninstalled Control Panel->Power->Schemes->Switch state to User Idle: Never Control Panel->Power->Schemes->Switch state to System Idle: Never

You can recover the default factory settings as you need or an unexpected problem occurs with the following steps:

ICP DAS Co., Ltd. Technical document

Classification	System and Application FAQ on WinCE PAC					No.	2-006-00
Author	Eric_Shiu	Version	1.0.0	Date	2018/04/27	Page	2/3

## Step1. Reboot in Safe mode

1.1. Turn the rotary switch on the device to "1", and then boot up the WinPAC/ViewPAC



1.2. After rebooting, Click the **"OK**" button.

Warning	
XPAC is running in SAFE MODE. If you want to set the registry back to the default settings, please do the following: Step 1. Turn the Rotary Switch to position 0 (normal mode) Step 2. Execute the XPAC Utility on the Desktop Step 3. Click File->"Save and Reboot" Step 4. The system will reboot and the default settings will take effect	

1.3. Turn the rotary switch to "**0**".



Classification	System and Application FAQ on WinCE PAC				No.	2-006-00	
Author	Eric_Shiu	Version	1.0.0	Date	2018/04/27	Page	3/3

## Step2. Recover the default factory settings

2.1. Start the WinPAC/ViewPAC Utility, and click "File" → "Save and Reboot" on the menu.

File	Help
Save	Э
Save	e and Reboot
<u>R</u> eb	oot
Rest E <u>x</u> it	ore Utility Default Settings:

2.2. Click the "Yes" button and wait for the device to reboot.

