

(P)ET-2218H/S1 Quick Start

v1.0, February 2025

Packing List

In addition to this guide, the package includes the following items:

(P)ET-2218H/S1 = (P)ET-2218H + CN-1825M



(P)ET-2218H *1



CN-1825M *1



Screw Driver *1


Technical Support

service@icpdas.com https://www.icpdas.com

Resources

How to search for drivers, manuals and spec information on ICP DAS website.

• For Mobile Web



• For Desktop Web





PRODUCTS SOLUTIONS NEWS & EVENTS SUPPORT CORPORAT

(P)ET-2218H/S1 Assembly Chart for (P)ET-2218H and CN-1825M

- 1. Insert the daughter board CN-1825M
- 2. Fasten the screws to secure the CN-1825M to (P)ET-2218H

1. Insert the CN-1825M



2. Fasten the screws to secure the CN-1825M

